HABS No. DE-249

Andrew Jackson Williams House
(Paul E. Bower, Jr., House)
2200 Newport Gap Pike (State Route 41)
South side of Newport Gap Pike approximately
.25 miles west of junction with Kirkwood Highway
(State Route 2)
Prices Corner Vicinity
New Castle County

Delaware

HABS DEL, 2-PRICO, 2-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS DEL, 2-PRICO,

ARCHITECTURAL DATA FORM

) -

STATE	COUNTY		TOWN OR VI	CINITY	
Delaware	New Castle Co	•	Prison Cor	mer Vicinity	
HISTORIC NAME OF STRUCTURE (INCL			ITITUES DUL	HABS NO.	
Andrew Jackson Williams House (New Castle County deeds and tax records) DE-249 SECONDARY OR COMMON NAMES OF STRUCTURE					
SECONDARY ON COMMENT WANTED OF STRICT ONE					
Paul E. Bower, Jr. House					
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)					
2200 Newport Gap Pike (State Route 41), south side approximately .25 miles west of junction with Kirkwood Highway (State Route 2)					
DATE OF CONSTRUCTION (INCLUDE SOURCE) ARCHITECT(S) (INCLUDE SOURCE)					
				,	
ca. 1870 (New Castle deeds and tax records)					
SIGNIFICANCE (ARCHITECTURAL ANO HISTORICAL, INCLUOE ORIGINAL USE OF STRUCTURE)					
This dwelling is a rural private home that was built for a middle-class family. It also documents the growth of the Greenbank area from a predominantly rural agricultural landscape					
into an industrial/manufacturing community and transportation center.					
STYLE (IF APPROPRIATE)					
Vernacular I-House with Greek Revival and Italinate elements					
MATERIAL DF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)					
Frame, fieldstone foundation (stuccoed on the interior, entire structure sheathed with German siding, asphalt shingle roof.					
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHEO FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)					
See Field Notes.	•				
EXTERIOR FEATURES OF NOTE					
Decorative elements include frieze boards and box cornices, eave brackets and partial					
return gable ends.					
INTERIOR FEATURES DF NOTE (DESCR	IBE FLOOR PLANS	, IF NOT SKETCHED)	<u> </u>		
See Field Notes.					
				•	
MA IOR AL TERATIONIC AND ADDITIONS	CWITH DATE				
MAJOR ALTERATIONS AND ADDITIONS		-t-m has rapless	J on corlic		
that was destroyed by fi	A shed-roof addition to the rear of the kitchen has replaced an earlier shed-roof addition that was destroyed by fire during the 1920s. Shed roof porch on northeast elevation				
replaced full length porch					
PRESENT CONDITION AND USE		-11-		mt = t =	
Recent vandalism has removed much of the structure's architectural elements. The house is in direct line of a proposed road improvement and will be demolished.					
OTHER INFORMATION AS APPROPRIATE					
Official Management and the second					
1					
SOURCES OF INFORMATION (INCLUOING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)					
The Delaware Statewide Comprehensive Historic Preservation Plan, Delaware Cultural Resource Survey, New Castle County Deeds/Tax Assessments for Christiana Hundred, United States					
Census Documents.				,	
COMPILER, AFFILIATION				DATE	
Stuart P. Dixon, Cheryl C. Por			itecture	14 February 1988	